



Note: no connection at R.O. terminal for non-rollout models

FIG.15 TYPICAL WIRING, HARDWARE TYPE 54,56